

Installation Guide



This procedure is designed as an installation aid. Skilled trades people that are familiar with general construction and electrical installation techniques should perform the installation. Licensed electricians should provide electrical installation connections. Installations and connections should be done in accordance with all national and local codes and permits. In no way is this document intended to construe warranty or fitness of use of the products described, nor is it intended to provide safety instruction for those installing the product.

WARNING

Before proceeding with installation or service maintenance of this product:


- Disconnect power to reduce electrical shock risk.
- Review the entire Installation Guide.
- Inspect this properly packaged product for any damage that may have occurred during transit.
- Verify product application complies with manufacturer design recommendations.
- Verify the availability of necessary tools and incidental material.
- Verify applicable code requirements. Field assembly and installation are subject to acceptance by local inspection authority.
- Appropriate safety equipment to be determined by end user, per applicable safety standards and precautions.

Mounting – Surface/Direct Mount




A

Step 1 – Use customer supplied 3/8" minimum self-tapping screws **A** to secure the bracket to the mounting surface.



B

Step 2 – Secure the bracket with screws, nuts and washers **B**.




C

Step 3 –

Connect wiring to customer supplied junction box. Connect the black wire **C** to hot wire, connect the white wire **C** to the neutral and connect the green wire **F** to the ground. Use customer supplied hardware to attach pendant to the junction box.

Note: If dimming option is used, connect the purple wire **C** to the supply dimming positive lead and connect the grey wire **C** to the supply dimming negative lead.


Mounting – Pendant Mount



D

E

Step 1 – Feed cable through customer supplied 3/4" O.D. pendant **D** and attached pendant **D** to pendant bracket **E**.



F

Step 2 –

Connect wiring to customer supplied junction box. Connect the black wire **F** to hot wire, connect the white wire **F** to the neutral and connect the green wire **F** to the ground. Use customer supplied hardware to attach pendant to the junction box.

Note: If dimming option is used, connect the purple wire **F** to the supply dimming positive lead and connect the grey wire **F** to the supply dimming negative lead.


Mounting – Suspension Mount



Step 1 – Feed suspension cable through four holes **G** on the mounting bracket.



Step 2 – Attach four rings **H** to the suspension cable and customer supplied eyebolts.



Step 3 –

Connect wiring to customer supplied junction box. Connect the black wire **J** to hot wire, connect the white wire **J** to the neutral and connect the green wire **J** to the ground. Use customer supplied hardware to attach pendant to the junction box.

Note: If dimming option is used, connect the purple wire **J** to the supply dimming positive lead and connect the grey wire **J** to the supply dimming negative lead.